
 英派尔伊拉克项目部 ENPAL IRAQ PROJECT DIVISION		信函/LETTER		项目名称(Project): Degassing Station Upgrading	
发至 (To)	CNOOC IRAQ LIMITED DS PMT	发自 (From)	ENPAL DS PMT		
主送 (Attn.)	Mr. Bai Gang / Mr. Meng Lei Mr. Hussam Jassem Mr. Mutaz	编制人 (Prepared By)	Ma Chi		
抄送 (Cc.)	Mr. Yang Tingsheng Mr. Yang Qing Mr. Dheyaa	发送日期 (Date)	11 th Aug. 2019		
页数 (Pages)	1 Pages	编号 (PMT/PMT Ref. No.)	ENPAL-726-CMIT-00.34 -034		
类别 For your	<input checked="" type="checkbox"/> Attention(Urgent) <input type="checkbox"/> Reply <input type="checkbox"/> Information <input type="checkbox"/> Approval <input type="checkbox"/> Review <input type="checkbox"/> Comment and Return Receipt				
主题 (Subject) :	Work Stoppage at BUN				
<p>To DS PMT/PMC</p> <p>Kindly inform that there was a work stoppage happened on Aug 11th at BUN new degassing station. Please see the attachment for your more information.</p> <p style="margin-left: 40px;">Attachment-1 LOST TIME SHEET</p> <p style="margin-left: 40px;">Attachment-2 Security breach incident Report</p>					
审核 Reviewed by	<i>Yn Hong</i>	批准 Approved by	<i>Wang Xinghe</i>	日期 Date	2019-8-11



KTI POLAND
PMC - HSE UNIT
LOST TIME SHEET FORM



Company	ENPAL
Site/Area	BUN
DATE:	11.08.2019

Company	ENPAL
Site/Area	BUN
DATE:	11.08.2019

Date:	11.08.19	11.08.19	11.08.19	11.08.19	11.08.19	11.08.19	11.08.19	11.08.19	11.08.19	11.08.19	11.08.19	Total Hours Stoppage/Day
Time Hour #	6:30-7:30	7:30-8:30	8:30-9:30	9:30-10:30	10:30-11:30	break	14:30-15:30	15:30-16:30	16:30-17:30	17:30-18:30		
SN cause description	P	P	P	P	P	P	P	P	P	P		
1	Local farmer stopped work at BUN.	P	P	1	1	1	1	1	1	1	1	7

Note: ENPAL is in the process of template hardening, the local stop our work. ENPAL will report to PMC/FCD for coordination in order to solve this issue. Involved OPF.

Legend: "P" = Present
 Legend: "1" = Hours Work Stoppage

Issued by: _____ Signature and Date: _____
 Approved by: _____ Signature and Date: _____

Handwritten signature
 2019-8-11



Incident Report

Report Date: Aug 11, 2019

CMIT -HSE-000-60.10-18MP16A-1(EN)

Date & Time of Occurrence:		Aug11, 2019, around 8:40am		Location:		BUN	
Incident Classification	<input type="checkbox"/> DAFW (Days Away From Work) Case		<input type="checkbox"/> First Aid		<input type="checkbox"/> Medical Treatment Case		
	<input type="checkbox"/> Material Loss/Property Damage/Business Interruption		<input type="checkbox"/> Fire/Explosion		<input type="checkbox"/> Vehicle Accident		
	<input type="checkbox"/> Occupational Health Illness		<input checked="" type="checkbox"/> Security Breach		<input type="checkbox"/> Environmental Impact		
Incident Severity Rate	<input type="checkbox"/> (Category 1 or 2) (≤ 2)			<input type="checkbox"/> Category (3, 4 or 5) (≥ 3)			
Fatality	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No		Number of Fatalities		N/A		
Injuries	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No		Number of Injured Persons		N/A		
Injured Persons/Fatalities	Name		Job Title		Company/Dept.		Injury or Fatality
	N/A		N/A		N/A		N/A
<u>Incident Description and resulted Consequences/ Impact/Damages or injuries:</u>							
<p>On dated Aug 11th 2019, some ENPAL workers carry out site camp preparation near BUN new degassing station; others are shoring up the formwork at BUN.</p> <p>Around 8:40am, one Iraqi farmer from the local tribe arrived on site and stopped our work. He said that the land was his and need compensation.</p> <p>ENPAL's employees stopped their work immediately due to the unsafe condition.</p>							
<u>Immediate Action(s):</u>							
ENPAL stopped their work immediately due to the unsafe condition.							
<u>Incident Cause(s):</u>							
N/A.							
<u>Next Action(s):</u>							
<ol style="list-style-type: none"> 1. Try to coordinate with local tribe. 2. Report to PMC/FCD for coordination to solve this issue. 							

Report Prepared by (Name/Department/ Signature):

ENPAL HSE Engineer: Hou Jinming